prep meeting

Computer controlled machining has to be on a machine where the sorter side is at least 1m!

This month we will be introduced to our global evaluator.

Revision #2
Created 2025-02-19 14:03:47 UTC by Ferdi
Updated 2025-02-19 15:38:08 UTC by Ferdi