

Troubleshooting

Carvera Makera

Machine coordinates in the software constantly increase

- just restart the machine, **ALSO DISCONNECT THE MACHINE FROM USB** and then restart the software

Toolchanger often failes on changeing the tool

- happens because the tools is not correctly inserted and can be solved by bending the metal clamp inwards

TODO IMAGE

Revision #3

Created 2025-07-21 13:35:39 UTC by Niclas

Updated 2026-02-12 18:46:04 UTC by Niclas